



Measuring MDT #1:

MDT Supply: #1, #1L closed

MDT Measure: #1, #3, #6, #1R closed and #1L open

#2L ... #10L closed, in order to polarize all the MDTs not under measurement

WTM Measure: #2, #5, #1R, #1L, #4 closed

HV / WTM Distribution Box

A. Cardini / 150999